

SanAir Technologies Laboratory

Analysis Report

prepared for

All Points Environmental, LLC

Report Date: 2/10/2017
Project Name: Old Gym - Kingsville
Project #: CA-022.027
SanAir ID#: 17004559



NVLAP LAB CODE 200870-0



Certification # 652931



License # LAB0166



804.897.1177

www.sanair.com



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

All Points Environmental, LLC
500 N. Water St
Ste. 605
Corpus Christi, TX 78401

February 10, 2017

SanAir ID # 17004559
Project Name: Old Gym - Kingsville
Project Number: CA-022.027

Dear AJ Medina,

We at SanAir would like to thank you for the work you recently submitted. The 40 sample(s) were received on Tuesday, February 07, 2017 via FedEx. The final report(s) is enclosed for the following sample(s): 51-100, 51-105, 51-109, 51-111, 51-113, 51-117, 51-122, 51-124, 51-128, 51-130, 51-135, 51-139, 51-141, 51-143, 51-145, 51-150, 51-154, 51-158, 51-160, 51-165, 51-167, 51-171, 51-174, 51-179, 51-182, 51-185, 51-188, 51-190, 51-196, 51-199, 51-201, 51-205, 51-208, 51-212, 51-216, 51-219, 51-220, 51-224, 51-228, 51-235.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:
- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

sample conditions:
40 sample(s) in Good condition



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrinho, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-100 / 17004559-001 12x12 Floor Tile/ West Locker Room, Floor Tile	White Non-Fibrous Homogeneous		100% Other		None Detected
51-100 / 17004559-001 12x12 Floor Tile/ West Locker Room, Mastic	Yellow Non-Fibrous Homogeneous		100% Other		None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-105 / 17004559-002 12x12 Floor Tile/ West Locker Room, Floor Tile	White Non-Fibrous Homogeneous		100% Other		None Detected
51-105 / 17004559-002 12x12 Floor Tile/ West Locker Room, Mastic	Yellow Non-Fibrous Homogeneous		100% Other		None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-109 / 17004559-003 12x12 Floor Tile/ West Locker Room	White Non-Fibrous Homogeneous		100% Other		None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-111 / 17004559-004 12x12 Floor Tile/ West Locker Room	Green Non-Fibrous Homogeneous		100% Other		None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-113 / 17004559-005 12x12 Floor Tile/ West Locker Room	Green Non-Fibrous Homogeneous		100% Other		None Detected

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrino, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-117 / 17004559-006 12x12 Floor Tile/ West Locker Room, Floor Tile	Green Non-Fibrous Homogeneous		100% Other	None Detected
51-117 / 17004559-006 12x12 Floor Tile/ West Locker Room, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-122 / 17004559-007 Pipe Wrap/ West Locker Room	White Fibrous Heterogeneous	60% Cellulose 15% Glass	25% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-124 / 17004559-008 Pipe Wrap/ West Locker Room	White Fibrous Heterogeneous	70% Cellulose 15% Glass	15% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-128 / 17004559-009 Pipe Wrap/ West Locker Room	White Fibrous Heterogeneous	70% Cellulose 15% Glass	15% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-130 / 17004559-010 Drywall/ Texture/ 2nd Floor Wall, Drywall	Off-White Non-Fibrous Homogeneous	2% Cellulose	98% Other	None Detected
51-130 / 17004559-010 Drywall/ Texture/ 2nd Floor Wall, Texture	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrinho, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-135 / 17004559-011 Drywall/ Texture/ 2nd Floor - Closet, Drywall	Off-White Non-Fibrous Homogeneous	3% Cellulose	97% Other	None Detected
51-135 / 17004559-011 Drywall/ Texture/ 2nd Floor - Closet, Texture	White Non-Fibrous Homogeneous		97% Other	3% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-139 / 17004559-012 Drywall/ Texture/ 2nd Floor - Closet, Drywall	Off-White Non-Fibrous Homogeneous	3% Glass	97% Other	None Detected
51-139 / 17004559-012 Drywall/ Texture/ 2nd Floor - Closet, Texture	White Non-Fibrous Homogeneous		97% Other	3% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-141 / 17004559-013 Linoleum/ 2nd Floor - Floor, Linoleum	Tan Non-Fibrous Heterogeneous		85% Other	15% Chrysotile
51-141 / 17004559-013 Linoleum/ 2nd Floor - Floor, Mastic	Tan Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-143 / 17004559-014 Linoleum/ 2nd Floor - Floor	Tan Non-Fibrous Heterogeneous	5% Cellulose	80% Other	15% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-145 / 17004559-015 Linoleum/ 2nd Floor - Floor, Linoleum	Tan Non-Fibrous Heterogeneous	5% Cellulose	80% Other	15% Chrysotile
51-145 / 17004559-015 Linoleum/ 2nd Floor - Floor, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrino, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
51-150 / 17004559-016 12x12 Floor Tile/ East Womens Restroom, Floor Tile	Brown Non-Fibrous Homogeneous		100% Other	None Detected
51-150 / 17004559-016 12x12 Floor Tile/ East Womens Restroom, Mastic	Black Non-Fibrous Homogeneous		98% Other	2% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
51-154 / 17004559-017 12x12 Floor Tile/ East Womens Restroom, Floor Tile	Brown Non-Fibrous Homogeneous		100% Other	None Detected
51-154 / 17004559-017 12x12 Floor Tile/ East Womens Restroom, Mastic	Black Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
51-158 / 17004559-018 12x12 Floor Tile/ East Womens Restroom, Floor Tile	Brown Non-Fibrous Homogeneous		100% Other	None Detected
51-158 / 17004559-018 12x12 Floor Tile/ East Womens Restroom, Mastic	Black Non-Fibrous Homogeneous		98% Other	2% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
51-160 / 17004559-019 12x12 Floor Tile/ East Womens Restroom, Floor Tile	White Non-Fibrous Homogeneous		100% Other	None Detected
51-160 / 17004559-019 12x12 Floor Tile/ East Womens Restroom, Mastic	Black Non-Fibrous Homogeneous		97% Other	3% Chrysotile

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017

Page 6 of 15



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrino, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-165 / 17004559-020 12x12 Floor Tile/ East Womens Restroom, Floor Tile	White Non-Fibrous Homogeneous		100% Other	None Detected
51-165 / 17004559-020 12x12 Floor Tile/ East Womens Restroom, Mastic	Black Non-Fibrous Homogeneous		98% Other	2% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-167 / 17004559-021 12x12 Floor Tile/ East Mens Restroom, Floor Tile	White Non-Fibrous Homogeneous		100% Other	None Detected
51-167 / 17004559-021 12x12 Floor Tile/ East Mens Restroom, Mastic	Black Non-Fibrous Homogeneous		95% Other	5% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-171 / 17004559-022 Mastic Packs/ Chalk Board - Weight Rm	Black Non-Fibrous Heterogeneous		92% Other	8% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-174 / 17004559-023 Mastic Packs/ Chalk Board - Weight Rm	Black Non-Fibrous Heterogeneous		92% Other	8% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-179 / 17004559-024 Mastic Packs/ Chalk Board - Weight Rm	Black Non-Fibrous Heterogeneous		92% Other	8% Chrysotile

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017

Page 7 of 15



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrino, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-182 / 17004559-025 Felt Paper/ Gym - Under Wood Floor	Black Fibrous Heterogeneous	50% Cellulose	50% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-185 / 17004559-026 Felt Paper/ Gym - Under Wood Floor	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-188 / 17004559-027 Felt Paper/ Gym - Under Wood Floor	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-190 / 17004559-028 Window Glazing/ Exterior Windows (New)	White Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-196 / 17004559-029 Window Glazing/ Exterior Windows (New)	White Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-199 / 17004559-030 Window Glazing/ Exterior Windows (New)	White Non-Fibrous Homogeneous		100% Other	None Detected

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017

Page 8 of 15



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrin, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-201 / 17004559-031 Window Caulking/ Exterior Windows (Old)	Grey Non-Fibrous Heterogeneous		100% Other		< 1% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-205 / 17004559-032 Window Caulking/ Exterior Windows (Old)	Grey Non-Fibrous Heterogeneous		98% Other		2% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-208 / 17004559-033 Window Caulking/ Exterior Windows (Old)	Grey Non-Fibrous Heterogeneous		100% Other		< 1% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-212 / 17004559-034 Gravel Roofing Material/ Roof	Various Non-Fibrous Heterogeneous	3% Cellulose 3% Glass	94% Other		None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-216 / 17004559-035 Gravel Roofing Material/ Roof	Various Non-Fibrous Heterogeneous	3% Cellulose 3% Glass	94% Other		None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
51-219 / 17004559-036 Gravel Roofing Material/ Roof	Various Non-Fibrous Heterogeneous	3% Cellulose 3% Glass	94% Other		None Detected

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrino, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-220 / 17004559-037 Parapit/ Roof, Rolled Roofing	Black Non-Fibrous Homogeneous	10% Glass	90% Other	None Detected
51-220 / 17004559-037 Parapit/ Roof, Coating	Silver Non-Fibrous Homogeneous		100% Other	None Detected
51-220 / 17004559-037 Parapit/ Roof, Felt	Black Fibrous Homogeneous	15% Cellulose	40% Other	45% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-224 / 17004559-038 Parapit/ Roof, Rolled Roofing	Black Non-Fibrous Homogeneous	10% Glass	90% Other	None Detected
51-224 / 17004559-038 Parapit/ Roof, Coating	Silver Non-Fibrous Homogeneous		100% Other	None Detected
51-224 / 17004559-038 Parapit/ Roof, Felt	Black Fibrous Homogeneous	15% Cellulose	40% Other	45% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-228 / 17004559-039 Parapit/ Roof, Rolled Roofing	Black Non-Fibrous Homogeneous	10% Glass	90% Other	None Detected
51-228 / 17004559-039 Parapit/ Roof, Coating	Silver Non-Fibrous Homogeneous		100% Other	None Detected
51-228 / 17004559-039 Parapit/ Roof, Felt	Black Fibrous Homogeneous	15% Cellulose	40% Other	45% Chrysotile

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017

Page 10 of 15



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

17004559

FINAL REPORT

Name: All Points Environmental, LLC
Address: 500 N. Water St
Ste. 605
Corpus Christi, TX 78401

Project Number: CA-022.027
P.O. Number:
Project Name: Old Gym - Kingsville

Collected Date: 2/3/2017
Received Date: 2/7/2017 10:30:00 AM
Report Date: 2/10/2017 5:47:18 PM
Analyst: Rouillard, Elliott
Sobrino, Sandra
Tallert, Jonathan
Toth, Elizabeth

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
51-235 / 17004559-040 Moisture Barrier/ Behind Brick	Black Non-Fibrous Homogeneous		100% Other	None Detected

Certification

Analyst: *Elizabeth Toth*
Analysis Date: 2/10/2017

Approved Signatory: *[Signature]*
Date: 2/10/2017

Page 11 of 15

Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983



1551 Oakbridge Drive Suite B
Powhatan, VA 23139
804-897-1177 / 888-895-1177
Fax 804-897-0070
www.sanair.com

Asbestos Chain of Custody

SanAir ID Number

17004559

Company: All Points Environmental, LLC	Project #: CA-022-027	Collected by: A. Welles Jr.
Address: 500 N. Water St., Ste 605	Project Name: Old Gym - Kingsville	Phone #: (361)882-3393
City, St., Zip: Corpus Christi, TX 78401	Date Collected: 02/03/17	Fax #: (361)883-1511
State of Collection: Account#: 300621	P.O. Number:	Email: allpointsez@gmail.com

Bulk			Air			Soil/Vermiculite		
ABB	PLM EPA 600/R-93/116	☒	ABA	PCM NIOSH 7400	☐	ABSE	PLM EPA 600/R-93/116 (Qual.)	☐
	Positive Stop	☐	ABA-2	OSHA w/ TWA*	☐	ABSP	PLM CARB 435 (LOD <1%)	☐
ABEPA	PLM EPA 400 Point Count	☐	ABTEM	TEM AHERA	☐	ABSP1	PLM CARB 435 (LOD 0.25%)	☐
ABB1K	PLM EPA 1000 Point Count	☐	ABATN	TEM NIOSH 7402	☐	ABSP2	PLM CARB 435 (LOD 0.1%)	☐
ABBEN	PLM EPA NOB	☐	ABT2	TEM Level II	☐			
ABBCH	TEM Chatfield	☐						
ABBTM	TEM EPA NOB	☐						
Water			New York ELAP			Dust		
ABHE	EPA 100.2	☐	PLM NY	PLM EPA 600/M4-82-020	☐	ABWA	TEM Wipe ASTM D-6480	☐
			ABEPA2	NY ELAP 198.1	☐	ABDMV	TEM Microvac ASTM D-5755	☐
			ABENY	NY ELAP 198.6 PLM NOB	☐	Matrix	Other	
			ABBNY	NY ELAP 198.4 TEM NOB	☐			☐

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☐
	2 Days ☐	3 Days ☒	4 Days ☐	5 Days ☐

Special Instructions

Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop
SI-100	White 12x12 Floor Tile / West Locker Room	Bulk			
SI-105					
SI-109					
SI-111	Green 12x12 Floor Tile / West Locker Room	Bulk			
SI-113					
SI-117					
SI-122	White pipe wrap / West Locker Room	Bulk			
SI-124					
SI-128					

Relinquished by	Date	Time	Received by	Date	Time
A. Welles Jr.	2/6/17	1650	CEV	2/7/17	10:30AM

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed to Recipient will be charged a \$10 shipping fee.

17004559

Sample #	Sample Identification/Location	Sample Type	Flow Rate*	Time* Start - Stop
51-130	Drywall/Texture / 2nd Floor Wall	Bulk		
51-135	↓ / ↓ - Closet	↓		
51-139	↓ / ↓	↓		
51-141	Stone Pattern Linoleum / 2nd Floor - Floor	Bulk		
51-143	↓ / ↓	↓		
51-145	↓ / ↓	↓		
51-150	Brown 12x12 Floor Tile / East Hall - By Restrooms	Bulk		
51-154	↓ / ↓	↓		
51-158	↓ / ↓	↓		
51-160	White 12x12 Floor Tile / East Womens Restroom	Bulk		
51-165	↓ / ↓	↓		
51-167	↓ / East Mens Restroom	↓		
51-171	Black Marble Rocks / Chalk board - Weight Rm.	Bulk		
51-174	↓ / ↓	↓		
51-179	↓ / ↓	↓		
51-182	Felt Paper / Gym - Under Wood Floor	Bulk		
51-185	↓ / ↓	↓		
51-188	↓ / ↓	↓		
51-190	Window Glazing / Exterior Windows (new)	Bulk		
51-196	↓ / ↓	↓		
51-199	↓ / ↓	↓		
51-201	Window Caulking / Exterior Windows (Old)	Bulk		
51-205	↓ / ↓	↓		
51-208	↓ / ↓	↓		

Special Instructions

Relinquished by	Date	Time	Received by	Date	Time
<i>A. Wells</i>	2/6/17	10:50	(CV)	2/7/17	10:30 AM

Unless scheduled, the turn around time for all samples received after 3 pm Friday will begin at 8 am Monday morning.

Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time.

Work with standard turn around time sent Priority Overnight and Billed to Recipient will be charged a \$10 shipping fee.

Page 2 of 3

Volume

[illegible]

Special Instructions

Relinquished by	Date	Time	Received by	Date	Time
<i>[Signature]</i>	2/3/17	1650	<i>[Signature]</i>	2/7/17	10:30Am

Unless scheduled, the turn around time for all samples received after 3 pm Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed to Recipient will be charged a \$10 shipping fee.

Page 3 of 5